



Reserve Study Full Study

Garland Meadows Homeowners' Association, Inc.

Draft 1

Published - March 25, 2021 Prepared for the December 31, 2021 Fiscal Year

Contact: Pioneer West Property Mngt

North Star Reserves

/ Boise, ID 83713 Office (208) 365-0977 Aaron@NorthStarReserves.com



Table of Contents

Section Report	Page
Reserve Study Summary	3
Expenditures	7
Expense Flow - Chart (30 Years in View)	16
Expenditures - Year Over Year (5 Years)	
Cash Flow - Annual	20
Balance Flow - Chart (30 Years in View)	22
Percent Funded - Cash Flow - Annual	23
Item Parameters - Detail	26
Item Parameters - Full Detail	31
Items Removed or Left Out of the Study	63
Glossary of Reserve Study Terms	64



Reserve Study Summary Full Study

Garland Meadows Homeowners' Association, Inc.

Published - March 25, 2021 Prepared for the December 31, 2021 Fiscal Year

Reserve Study Summary

A Reserve Study was conducted of Garland Meadows Homeowners' Association, Inc. (the "**Condominium**"). A **Full Study** includes an on-site review upon where the following tasks are performed:

- Development of a reserve component inventory;
- Condition assessment based upon on-site visual observation;
- Useful life and valuation estimates;
- Evaluation of fund status and creation of a funding plan.

Garland Meadows Homeowners' Association, Inc. is a community with a total of 26 Units.

Physical Inspection

North Star Reserves ("**NSR**") conducted a physical inspection of the Condominium. The inspection encompassed those major components that the Condominium is required to maintain. For this study components are determined to be major components if:

- 1. As of the date of the study, they have a remaining useful life of less than 30 years, and a value greater than \$500.
- 2. Such additional components, if any, determined by the Board of Directors.

During the inspection, NSR utilized the services of our own construction cost estimator. In addition, independent contractors were retained to render opinions on selected components.

Supplemental information to the physical inspection may have been obtained from the following sources:

- 1. Project plans where available.
- 2. Maintenance records of the reserve components where available.
- 3. Condominium board members, management and staff.

Summary of Reserves

For the first year of the Reserve Study, the reserve contribution is based upon the existing budget and conversations with the property manager and/or appointed Association representative. In addition NSR relied on the Condominium to provide an accurate Beginning Reserve Balance.

The status of the Condominium's reserves, as reflected in the following Reserve Study, is as follows:

- 1. The Expenditure Forecast of the following Reserve Study identifies the major components which the Condominium is obligated to repair, replace, restore or maintain, as determined in accordance with the criteria specified above, and specifies for each such component:
 - Its current estimated replacement cost;
 - Its estimated useful life; and
 - Its estimated remaining useful life.



- 2. It is estimated that the total cash reserves necessary to repair, replace, restore or maintain such major components (in the aggregate) during and at the end of their first remaining useful life is \$721,686.
 - [For purposes of this calculation, "necessary" is defined as the Fully Funded Balance (FFB) (Component Future Cost ÷ Useful Life × Effective Age, including a provision for interest and inflation in future years.)]
 - See "FULLY FUNDED BALANCE" in the *Glossary of Reserve Study Terms* on the final pages of this study.
 - Inflation Rate for the this study is calculated at **2.50%**.
- 3. The current amount of accumulated cash reserves actually set aside to repair, replace, restore, or maintain such major components as of the fiscal year ending December 31, 2021 is estimated to be \$41,021, constituting 7.95% of the total expenditures anticipated for all such major components through their first end of useful life replacement.
- 4. Based upon the schedule of annual reserve contributions necessary to defray the cost of repairing, replacing, restoring or maintaining such major components in the years such expenditures are estimated to be required, it is estimated that annual reserve contributions in the initial amount of \$41,600 for the fiscal year ending December 31, 2021 (the first full fiscal year following first distribution of this report) will be necessary in order to meet all such reserve expenditures when they are projected to come due.

Funding Assessment

Based on the 30 year cash flow projection, the Condominium's reserves appear **inadequately** funded as the reserve fund ending balances remain **negative** throughout the replacement of most major components during the next 30 years. **For this reason, increased contributions have been outlined to meet future expenditures.**

Idaho statute imposes no reserve funding level requirements nor does it address funding level adequacy, and although one or more of the reserve fund percentages expressed in this report may be less than one hundred percent, those percentages do not necessarily indicate that the Condominium's reserves are inadequately funded.

Percent Funded Status

Based on paragraphs 1 - 3 above, the Condominium is **inadequately** funded.

The following illustrates the next fiscal year recommended contribution and ending balance:

		Annual Contribution	-	End Balance	-	% Funded
•	Year 1:	\$41,600		<i>\$58,625</i>		5.68%
•	Year 2:	\$62,400		<i>\$73,633</i>		7.95%



Methodology

The above recommended reserve contribution for the next fiscal year (and future fiscal years as outlined in the *Cash Flow - Annual* forecast report) was developed using the cash flow method. This is a method of developing a reserve funding plan where the contributions to the reserve fund are designed to offset the variable annual expenditures from the reserve fund. Different reserve funding plans are tested against the anticipated schedule of reserve expenses until the desired funding goal is achieved.

Funding Goals

The funding goal employed for Garland Meadows Homeowners' Association, Inc. is

Threshold Funding: Establishing a Reserve funding goal of keeping the Reserve balance above a specified dollar or Percent Funded amount. Depending on the threshold, this may be more or less conservative than "Fully Funding.

Limitations

The intention of the Reserve Study is to forecast the Condominium's ability to repair or replace major components as they wear out in future years. The Reserve Study is not an engineering report, and no destructive testing was performed. The costs outlined in the study are for budgetary and planning purposes only, and actual bid costs would depend upon the defined scope of work at the time repairs are made. Also, any latent defects are excluded from this report.

Statutory Disclosures

Compliance

The Reserve Study complies with or exceeds all applicable statutes, if any

Supplemental Disclosures

General:

NSR has no other involvement(s) with the Condominium which could result in actual or perceived conflicts of interest.

Completeness:

NSR has found no material issues which, if not disclosed, would cause a distortion of the Condominium's situation.

Reliance on Client Data:

Information provided by the official representative of the Condominium regarding financial, physical, quantity, or historical issues are deemed reliable by NSR.



Scope:

This Reserve Study is a reflection of information provided to NSR and assembled for the Condominium's use, not for the purpose of performing an audit, quality/forensic analysis, health and safety inspection, or background checks of historical records.

Reserve Balance:

The actual beginning reserve fund balance in this Reserve Study is based upon information provided and was not audited.

Reserve Projects:

Information provided about reserve projects will be considered reliable. Any on-site inspection should not be considered a project audit, quality inspection, or health and safety review.





Analysis Date - January 1, 2021

Page 7

Subcategory	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Concrete										
Concrete Repair		2,071		1,088						2,523
U-Channel & Curbing		1,242			1,338			1,441		
	0	3,313	0	1,088	1,338	0	0	1,441	0	2,523
Doors										
Doors - Exterior						10,688				
Doors - Sliding Glass				48,090						
	0	0	0	48,090	0	10,688	0	0	0	0
Furnishings & Décor										
Furnishings & Décor			2,653							
	0	0	2,653	0	0	0	0	0	0	0
Gutters & Downspouts										
Gutters & Downspouts						4,951				
Heat Tape				3,808						4,416
	0	0	0	3,808	0	4,951	0	0	0	4,416
Irrigation										
Landscaping - Timers		517		544		571		600		630
	0	517	0	544	0		0	600	0	630
Landscaping										
Contingency - Landscaping			1,592			1,714			1,846	
Landscaping - Beds & Shrubs	1,010		1,061		1,115		5,272		1,231	
Trees - Maintenance		3,106					3,515			
Trees - Replacement							2,636			
	1,010	3,106	2,653	0	1,115	1,714	11,423	0	3,077	0



Analysis Date - January 1, 2021

Page 8

Subcategory	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Painting										
Painting - Building Exterior		7,042	7,218	7,398	7,583	3,886				
	0	7,042	7,218	7,398	7,583	3,886	0	0	0	0
Paving										
Asphalt - Crackfill		1,155			1,244			1,340		
Asphalt - Repairs		3,081						3,574		
Asphalt - Sealing		1,926						2,233		
	0	6,163	0	0	1,244	0	0	7,148	0	0
Reserve Study										
Reserve Study Update		456	468	479	491	3,360	516	529	542	556
	0	456	468	479	491	3,360	516	529	542	556
Roofing										
Roofing - 30-yr Compositional	22,985	23,559				137,458				
	22,985	23,559	0	0	0	137,458	0	0	0	0
Shade Structures										
Pavilion - Maintenance						1,828				
	0	0	0	0	0	1,828	0	0	0	0
Staining										
Staining - Exterior		3,231								3,936
	0	3,231	0	0	0	0	0	0	0	3,936
Structural Repairs										
Contingency - Building Exterior				2,393						
Siding & Trim			5,095					5,764		
Soffits & Fascia				2,720					3,077	
	0	0	5,095	5,113	0	0	0	5,764	3,077	0





Analysis Date - January 1, 2021

										Page 9
			Exp	enditure	S					
Subcategory	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Utility Infrastructure										
Utility Infrastructure								7,806		
	0	0	0	0	0	0	0	7,806	0	0
	23,995	47,392	18,088	66,523	11,773	164,461	11,940	23,290	6,697	12,063



Analysis Date - January 1, 2021

Page 10

Subcategory	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Concrete										
Concrete Repair				1,392				3,074		
U-Channel & Curbing	1,551			1,671			1,799			1,938
	1,551	0	0	3,064	0	0	1,799	3,074	0	1,938
Furnishings & Décor										
Furnishings & Décor	3,233								3,939	
	3,233	0	0	0	0	0	0	0	3,939	0
Garage										
Garage Door - Metal, Single Bay	21,857									
	21,857	0	0	0	0	0	0	0	0	0
Gutters & Downspouts										
Heat Tape						5,121				
	0	0	0	0	0	5,121	0	0	0	0
Irrigation										
Landscaping - Timers		662		696		731		768		807
	0	662	0	696	0	731	0	768	0	807
Landscaping										
Contingency - Landscaping		1,988			2,141			2,306		
Landscaping - Beds & Shrubs	1,293		1,358		6,424		1,499		1,575	
Trees - Maintenance		3,976					4,499			
Trees - Replacement					3,212					
	1,293	5,965	1,358	0	11,777	0	5,999	2,306	1,575	0



Analysis Date - January 1, 2021

Page 11

Subcategory	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Lighting										
Lighting - Exterior		11,374								
	0	11,374	0	0	0	0	0	0	0	0
Painting										
Painting - Building Exterior		9,014	9,239	9,470	9,707	4,975				
	0	9,014	9,239	9,470	9,707	4,975	0	0	0	0
Paving										
Asphalt - Crackfill	1,443			1,554			1,673			1,802
Asphalt - Overlay	19,244									
Asphalt - Repairs				4,144						4,806
Asphalt - Sealing				2,590						3,004
Pavers - Brick						702				
	20,687	0	0	8,289	0	702	1,673	0	0	9,613
Reserve Study										
Reserve Study Update	3,802	584	599	614	629	4,302	661	677	694	712
	3,802	584	599	614	629	4,302	661	677	694	712
Shade Structures										
Pavilion - Maintenance		2,121						2,459		
	0	2,121	0	0	0	0	0	2,459	0	0
Staining										
Staining - Exterior								4,796		
	0	0	0	0	0	0	0	4,796	0	0





Analysis Date - January 1, 2021

Page 12

Subcategory	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Structural Repairs								•		
Contingency - Building Exterior	2,845							3,382		
Siding & Trim		63,631	71,744	66,852	68,524	70,237	71,993	81,172	75,637	54,270
Soffits & Fascia				3,481					3,939	
	2,845	63,631	71,744	70,334	68,524	70,237	71,993	84,554	79,577	54,270
Utility Infrastructure										
Utility Infrastructure								9,992		
	0	0	0	0	0	0	0	9,992	0	0
Windows										
Windows		6,959	7,133	7,312	7,494	7,682	7,874	8,071	8,272	
	0	6,959	7,133	7,312	7,494	7,682	7,874	8,071	8,272	0
	55,271	100,313	90,076	99,782	98,133	93,752	90,001	116,702	94,060	67,341



Analysis Date - January 1, 2021

Page 13

Subcategory	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Concrete										
Concrete Repair				1,782		3,746				
U-Channel & Curbing			2,087			2,247			2,420	
	0	0	2,087	1,782	0	5,993	0	0	2,420	0
Doors										
Doors - Sliding Glass									89,157	
	0	0	0	0	0	0	0	0	89,157	0
Furnishings & Décor										
Furnishings & Décor							4,799			
	0	0	0	0	0	0	4,799	0	0	0
Gutters & Downspouts							,			
Gutters & Downspouts									2,299	
Heat Tape		5,939						6,887		
	0	5,939			0	0	0	6,887	2,299	0
Irrigation										
Landscaping - Timers		848		891		936		983		1,033
	0	848	0	891	0	936	0	983		1,033
Landscaping										
Contingency - Landscaping	2,483			2,674			2,879			3,101
Landscaping - Beds & Shrubs	1,655		7,827		1,827		1,919		2,017	
Trees - Maintenance		5,090					5,759			
Trees - Replacement			3,913							
	4,138	5,090	11,740	2,674	1,827	0	10,559	0	2,017	3,101



Analysis Date - January 1, 2021

Page 14

Subcategory	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Lighting										
Lighting - Exterior				15,296						
	0	0	0	15,296	0	0	0	0	0	0
Painting										
Painting - Building Exterior		11,539	11,827	12,123	12,426	6,368				
	0	11,539	11,827	12,123	12,426	6,368	0	0	0	0
Paving										
Asphalt - Crackfill			1,941			2,090			2,251	
Asphalt - Repairs						5,574				
Asphalt - Sealing						3,484				
	0	0	1,941	0	0	11,148	0	0	2,251	0
Reserve Study										
Reserve Study Update	4,867	748	767	786	805	5,506	846	867	889	911
	4,867	748	767	786	805	5,506	846	867	889	911
Roofing										
Roofing - 30-yr Compositional									91,779	
	0	0	0	0	0	0	0	0	91,779	0
Shade Structures										
Pavilion - Maintenance				2,852						3,308
	0	0	0	2,852	0	0	0	0	0	3,308
Staining										
Staining - Exterior						5,844				
	0	0	0	0	0	5,844	0	0	0	0





Analysis Date - January 1, 2021

Page 15


Subcategory	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Structural Repairs										_
Contingency - Building Exterior					4,020					
Siding & Trim			8,349					9,446		
Soffits & Fascia				4,457					5,042	
	0	0	8,349	4,457	4,020	0	0	9,446	5,042	0
Utility Infrastructure										
Utility Infrastructure								12,791		
-	0	0	0	0	0	0	0	12,791	0	0
	9,006	24,166	36,712	40,864	19,080	35,799	16,206	30,977	195,858	8,355



Analysis Date - January 1, 2021

Page 16

Expense Flow - Chart (30 Years in View)





Analysis Date - January 1, 2021

Page 17

Expenditures - Year Over Year (5 Years)

Subcategor	ту		Service	Estimated		
Date	Reserve Item	Location	Date	Life	Current Cost	Expenditure
V 2024						
Year: 2021 Landscaping						
	Landscaping - Beds & Shrubs	Common Area	06/01/2019	2:00	\$ 1,000.00	\$ 1,010.34
00,01,2021	Landscaping Beds & Sinds	common / wed	00,01,2013		1,000.00	1,010.34
Roofing				_		
•	Roofing - 30-yr Compositional	Common Area	06/01/1996	25:00	\$ 22,750.00	\$ 22,985.27
				_	22,750.00	22,985.27
Year: 2022						
Concrete						
06/01/2022	Concrete Repair	Common Area	06/01/1996	26:00	\$ 2,000.00	\$ 2,071.20
06/01/2022	U-Channel & Curbing	Common Area	06/01/2010	12:00	1,200.00	1,242.72
				_	3,200.00	3,313.92
Irrigation						
06/01/2022	Landscaping - Timers	Common Area	06/01/2020	2:00	\$ 500.00	\$ 517.80
				_	500.00	517.80
Landscaping						
06/01/2022	Trees - Maintenance	Common Area	06/01/2017	5:00	\$ 3,000.00	\$ 3,106.80
				_	3,000.00	3,106.80
Painting						
06/01/2022	Painting - Building Exterior	Common Area	06/01/1996	26:00	\$ 3,400.00	\$ 3,521.04
06/01/2022	Painting - Building Exterior	Common Area	06/01/1996	26:00	3,400.00	3,521.04
				_	6,800.00	7,042.08
Paving						
06/01/2022	Asphalt - Crackfill	Common Area	06/01/1996	26:00	\$ 1,116.00	\$ 1,155.73
	Asphalt - Repairs	Common Area	06/01/1996	26:00	2,976.00	3,081.95
06/01/2022	Asphalt - Sealing	Common Area	06/01/1996	26:00	1,860.00	1,926.22
				_	5,952.00	6,163.90
Reserve Study	У					
06/01/2022	Reserve Study Update	Common Area	06/01/2021	1:00	\$ 441.00	\$ 456.70
				_	441.00	456.70
Roofing						
06/01/2022	Roofing - 30-yr Compositional	Common Area	06/01/1996	26:00	\$ 22,750.00	\$ 23,559.91
				_	22,750.00	23,559.91
Staining						
06/01/2022	Staining - Exterior	Common Area	06/01/2014	8:00	\$ 3,120.00	\$ 3,231.07



Analysis Date - January 1, 2021

Page 18

Subcatego	ry		Service	Estimated		
Date	Reserve Item	Location	Date	Life	Current Cost	Expenditure
				_	3,120.00	3,231.07
Year: 2023	}					
Furnishings 8	& Décor					
06/01/2023	Furnishings & Décor	Common Area	06/01/2015	8:00	\$ 2,500.00	\$ 2,653.73
				_	2,500.00	2,653.73
Landscaping						
	Contingency - Landscaping	Common Area	06/01/2020	3:00	\$ 1,500.00	\$ 1,592.24
	Landscaping - Beds & Shrubs	Common Area	06/01/2021	2:00	1,000.00	1,061.49
				_	2,500.00	2,653.73
Painting				-		
•	Painting - Building Exterior	Common Area	06/01/1996	27:00	\$ 3,400.00	\$ 3,609.07
	Painting - Building Exterior	Common Area	06/01/1996	27:00	3,400.00	3,609.07
				_	6,800.00	7,218.14
Reserve Stud	h.			_		
	Reserve Study Update	Common Area	06/01/2021	2:00	\$ 441.00	\$ 468.12
00/01/2023	Reserve Study Opulate	Common Area	00/01/2021		441.00	468.12
				_		100.12
Structural Re						
06/01/2023	Siding & Trim	Common Area	06/01/2018	5:00	\$ 4,800.00	\$ 5,095.15
				_	4,800.00	5,095.15
Year: 2024	L					
Concrete						
06/01/2024	Concrete Repair	Common Area	06/01/2014	10:00	\$ 1,000.00	\$ 1,088.03
				_	1,000.00	1,088.03
Doors						
06/01/2024	Doors - Sliding Glass	Common Area	06/01/1996	28:00	\$ 44,200.00	\$ 48,090.82
				_	44,200.00	48,090.82
Cuttom 8 Do				_		
Gutters & Do	•	Common Area	06/01/2018	6:00	\$ 3,500.00	\$ 3,808.10
06/01/2024	Heat Tape	Common Area	06/01/2018	6:00	3,500.00	3,808.10
				_	3,300.00	3,800.10
Irrigation						
06/01/2024	Landscaping - Timers	Common Area	06/01/2022	2:00	\$ 500.00	\$ 544.01
				=	500.00	544.01
Painting						
06/01/2024	Painting - Building Exterior	Common Area	06/01/1996	28:00	\$ 3,400.00	\$ 3,699.29
06/01/2024	Painting - Building Exterior	Common Area	06/01/1996	28:00	3,400.00	3,699.29



Analysis Date - January 1, 2021

Page 19

Subcatego	ту		Service	Estimated		
Date	Reserve Item	Location	Date	Life	Current Cost	Expenditure
				<u> </u>	6,800.00	7,398.58
Reserve Stud	у				_	
06/01/2024	Reserve Study Update	Common Area	06/01/2021	3:00	\$ 441.00	\$ 479.82
				_	441.00	479.82
Structural Re	pairs					
06/01/2024	Contingency - Building Exterior	Common Area	06/01/2017	7:00	\$ 2,200.00	\$ 2,393.66
06/01/2024	Soffits & Fascia	Common Area	06/01/1996	28:00	2,500.00	2,720.07
					4,700.00	5,113.73
Year: 2025						
Concrete						
06/01/2025	U-Channel & Curbing	Common Area	06/01/2022	3:00	\$ 1,200.00	\$ 1,338.27
					1,200.00	1,338.27
Landscaping				_		
. •	Landscaping - Beds & Shrubs	Common Area	06/01/2023	2:00	\$ 1,000.00	\$ 1,115.23
				_	1,000.00	1,115.23
B. 1. 11				_		
Painting	Painting - Building Exterior	Common Area	06/01/1996	29:00	\$ 3,400.00	\$ 3,791.78
	Painting - Building Exterior	Common Area	06/01/1996	29:00	3,400.00	3,791.78
00/01/2023	Tainting Building Exterior	common Arca	00/01/1550		6,800.00	7,583.56
				_		
Paving						
06/01/2025	Asphalt - Crackfill	Common Area	06/01/2022	3:00	\$ 1,116.00	\$ 1,244.59
				_	1,116.00	1,244.59
Reserve Stud	у					
06/01/2025	Reserve Study Update	Common Area	06/01/2021	4:00	\$ 441.00	\$ 491.82
				_	441.00	491.82



Analysis Date - January 1, 2021

Page 20

Cash Flow - Annual

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
Begin Balance	41,021	58,625	73,633	117,945	113,822	164,448	71,747	131,566	180,036	245,098
Contribution	41,600	62,400	62,400	62,400	62,400	71,760	71,760	71,760	71,760	78,936
Average Per Unit	1,600	2,400	2,400	2,400	2,400	2,760	2,760	2,760	2,760	3,036
Percent Change	0.00%	50.00%	0.00%	0.00%	0.00%	15.00%	0.00%	0.00%	0.00%	10.00%
Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	23,995	47,392	18,088	66,523	11,773	164,461	11,940	23,290	6,697	12,063
Ending Balance	58,625	73,633	117,945	113,822	164,448	71,747	131,566	180,036	245,098	311,971
	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
Begin Balance	311,971	335,635	314,258	303,118	290,165	278,861	271,939	268,767	247,577	249,030
Contribution	78,936	78,936	78,936	86,829	86,829	86,829	86,829	95,512	95,512	95,512
Average Per Unit	3,036	3,036	3,036	3,339	3,339	3,339	3,339	3,673	3,673	3,673
Percent Change	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%
Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	55,271	100,313	90,076	99,782	98,133	93,752	90,001	116,702	94,060	67,341
Ending Balance	335,635	314,258	303,118	290,165	278,861	271,939	268,767	247,577	249,030	277,200





Analysis Date - January 1, 2021

Page 21


	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
Begin Balance	277,200	363,707	444,605	512,956	577,155	663,138	742,910	842,274	926,867	846,578
Contribution	95,512	105,063	105,063	105,063	105,063	115,570	115,570	115,570	115,570	127,127
Average Per Unit	3,673	4,040	4,040	4,040	4,040	4,445	4,445	4,445	4,445	4,889
Percent Change	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%
Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	9,006	24,166	36,712	40,864	19,080	35,799	16,206	30,977	195,858	8,355
Ending Balance	363,707	444,605	512,956	577,155	663,138	742,910	842,274	926,867	846,578	965,351



Analysis Date - January 1, 2021

Page 22

Balance Flow - Chart (30 Years in View)





Analysis Date - January 1, 2021

Page 23

Percent Funded - Cash Flow - Annual

	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030
100% Funded	721,686	737,792	733,375	759,949	740,294	777,187	665,417	708,928	741,692	791,520
Percent Funded	5.68%	7.95%	10.04%	15.52%	15.38%	21.16%	10.78%	18.56%	24.27%	30.97%
Begin Balance	41,021	58,625	73,633	117,945	113,822	164,448	71,747	131,566	180,036	245,098
Contribution	41,600	62,400	62,400	62,400	62,400	71,760	71,760	71,760	71,760	78,936
Average Per Unit	1,600	2,400	2,400	2,400	2,400	2,760	2,760	2,760	2,760	3,036
Percent Change	0.00%	50.00%	0.00%	0.00%	0.00%	15.00%	0.00%	0.00%	0.00%	10.00%
Special Assessment	0	0	0	0	0	0	0	0	0	0
Interest	0	0	0	0	0	0	0	0	0	0
Less Tax on Interest	0	0	0	0	0	0	0	0	0	0
Net Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	23,995	47,392	18,088	66,523	11,773	164,461	11,940	23,290	6,697	12,063
Less Deferred Expenditur	0	0	0	0	0	0	0	0	0	0
Ending Balance	58,625	73,633	117,945	113,822	164,448	71,747	131,566	180,036	245,098	311,971



Analysis Date - January 1, 2021

Page 24

Percent Funded - Cash Flow - Annual

	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040
100% Funded	836,243	839,053	799,749	774,156	742,436	716,104	697,885	687,107	653,779	647,266
Percent Funded	37.31%	40.00%	39.29%	39.15%	39.08%	38.94%	38.97%	39.12%	37.87%	38.47%
Begin Balance	311,971	335,635	314,258	303,118	290,165	278,861	271,939	268,767	247,577	249,030
Contribution	78,936	78,936	78,936	86,829	86,829	86,829	86,829	95,512	95,512	95,512
Average Per Unit	3,036	3,036	3,036	3,339	3,339	3,339	3,339	3,673	3,673	3,673
Percent Change	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%
Special Assessment	0	0	0	0	0	0	0	0	0	0
Interest	0	0	0	0	0	0	0	0	0	0
Less Tax on Interest	0	0	0	0	0	0	0	0	0	0
Net Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	55,271	100,313	90,076	99,782	98,133	93,752	90,001	116,702	94,060	67,341
Less Deferred Expenditur	0	0	0	0	0	0	0	0	0	0
Ending Balance	335,635	314,258	303,118	290,165	278,861	271,939	268,767	247,577	249,030	277,200



Analysis Date - January 1, 2021

Page 25

Percent Funded - Cash Flow - Annual

	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050
100% Funded	670,724	753,801	822,197	878,898	932,522	1,008,709	1,068,956	1,149,445	1,215,829	1,121,656
Percent Funded	41.33%	48.25%	54.08%	58.36%	61.89%	65.74%	69.50%	73.28%	76.23%	75.48%
Begin Balance	277,200	363,707	444,605	512,956	577,155	663,138	742,910	842,274	926,867	846,578
Contribution	95,512	105,063	105,063	105,063	105,063	115,570	115,570	115,570	115,570	127,127
Average Per Unit	3,673	4,040	4,040	4,040	4,040	4,445	4,445	4,445	4,445	4,889
Percent Change	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%	0.00%	0.00%	0.00%	10.00%
Special Assessment	0	0	0	0	0	0	0	0	0	0
Interest	0	0	0	0	0	0	0	0	0	0
Less Tax on Interest	0	0	0	0	0	0	0	0	0	0
Net Interest	0	0	0	0	0	0	0	0	0	0
Less Expenditures	9,006	24,166	36,712	40,864	19,080	35,799	16,206	30,977	195,858	8,355
Less Deferred Expenditur	0	0	0	0	0	0	0	0	0	0
Ending Balance	363,707	444,605	512,956	577,155	663,138	742,910	842,274	926,867	846,578	965,351



Analysis Date - January 1, 2021

Page 26

Item Parameters - Detail

Concrete Repair	Subcategory			Service				Adj	Rem	
Concrete Repair		Location	Desc.	Date	Basis Cost	Quantity	Current Cost	_	Life	Future Cost
Concrete Repair	Noser to Item			- Dutc	<u> </u>	Quarterty	- Current Cose			1 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
Concrete Repair	Concrete									
Common C				25/24/4225	4		40000			4
Channel & Curbing Common Ar Common A			•							
Doors Exterior	·									
Power Powe	U-Channel & Curbing	Common Ar	U-Channel	06/01/2010	1,200.00	1 Allowanc		12:00	1:05 _	
Doors - Exterior	Dears						4,200			4,401
Doors - Extenor Common Ar Garge Do 06/01/1996 275.00 8 Each 2,200 30.00 5.05 2,514				25/24/4225	4		4= 4=0			40.400
Path										
Pumishings & Décor Common Ar Pavilion Fu G/01/2015 \$2,500.00 1 Allowanc \$52,500 1.00 2.05			•							
Furnishings & Decor	Doors - Sliding Glass	Common Ar	Glass Door	06/01/1996	850.00	52 Each		28:00	3:05 _	
Furnishings & Décor	Fuunishings 9 Dásau						53,550			58,778
Composition Common Ar Garage Door - Metal, Single Bay Common Ar Bidg A Gutt Collision Common Ar Bidg A Gutt Collision Common Ar Bidg B Gutt Collision Collision Common Ar Bidg B Gutt Collision Collis	-		D ::: -	06/04/2045	4 2 500 00	4.411	4.2.500	0.00	2.05	42.552
Garage Door - Metal, Single Bay	Furnishings & Decor	Common Ar	Pavilion Fu	06/01/2015	\$ 2,500.00	1 Allowanc		8:00	2:05	
Garage Door - Metal, Single Bay Common Ar Garage Doo (6/01/1996 \$650.00 26 Each 16,900 35.00 10.00 21.857 2	_						2,500			2,653
Control Cont	-									
Common Ar	Garage Door - Metal, Single Bay	Common Ar	GarageDoo	06/01/1996	\$ 650.00	26 Each		35:00	10:05	
Gutters & Downspouts Common Ar Bldg A Gutt Of/01/1996 \$9.50 60 Linear F \$700 30:00 \$0.50 \$6.51							16,900			21,857
Gutters & Downspouts Common Ar Bldg B Gutt G/01/2019 9.50 60 Linear F 570 30:00 28:05 1,149	•									
Gutters & Downspouts	•	Common Ar	Bldg A Gutt	06/01/1996	\$ 9.50	60 Linear F	\$ 570	30:00	5:05	\$ 651
Gutters & Downspouts	Gutters & Downspouts	Common Ar	Bldg B Gutt		9.50	60 Linear F	570	30:00	28:05	1,149
Gutters & Downspouts Common Ar Bldg E Gutt 06/01/2019 9.50 60 Linear F 570 30:00 28:05 1,149 Gutters & Downspouts Common Ar Bldg E Gutt 06/01/1996 9.50 60 Linear F 570 30:00 5:05 651 Gutters & Downspouts Common Ar Bldg E Gutt 06/01/1996 9.50 60 Linear F 570 30:00 5:05 651 Gutters & Downspouts Common Ar Bldg B Gutt 06/01/1996 9.50 06 Linear F 570 30:00 5:05 651 Gutters & Downspouts Common Ar Bldg B Gutt 06/01/1996 9.50 06 Linear F 570 30:00 5:05 1,042 Heat Tape Common Ar Beat Tape 06/01/2018 3,500.00 1 Allowanc 3,500 6:00 3:05 3,808 Irigation Common Ar Timer Repl 06/01/2020 \$ 500.00 1 Allowanc \$ 50.00 1:05 \$ 517 Landscaping - Timers Common Ar Landscapi	Gutters & Downspouts	Common Ar	Bldg C Gutt		9.50	60 Linear F	570		5:05	651
Gutters & Downspouts Common Ar Bldg F Gutt 06/01/1996 9.50 60 Linear F 570 30:00 5:05 651 Gutters & Downspouts Common Ar Bldg G Gut 06/01/1996 9.50 60 Linear F 570 30:00 5:05 651 Gutters & Downspouts Common Ar Garage Gut 06/01/1996 9.50 60 Linear F 912 30:00 5:05 1,042 Heat Tape Common Ar Heat Tape 06/01/2018 3,500.00 1 Allowanc 3,500 6:00 3:05 3,808 Irrigation Landscaping - Timers Common Ar Timer Repl 06/01/2020 \$500.00 1 Allowanc \$500 2:00 1:05 \$517 Landscaping - Timers Common Ar Landscape 06/01/2020 \$1,500.00 1 Allowanc \$500 2:00 1:05 \$1,500 Landscaping - Eedes & Shrubs Common Ar Bed&Shrub 06/01/2020 \$1,500.00 1 Allowanc \$1,00 2:00 0:05 \$1,1	Gutters & Downspouts	Common Ar	Bldg D Gutt		9.50		570	30:00	5:05	651
Gutters & Downspouts Common Ar Bidg G Gut 06/01/1996 9.50 60 Linear F 570 30:00 5:05 651	Gutters & Downspouts	Common Ar	Bldg E Gutt	06/01/2019	9.50	60 Linear F	570	30:00	28:05	1,149
Gutters & Downspouts	Gutters & Downspouts	Common Ar	Bldg F Gutt	06/01/1996	9.50	60 Linear F	570	30:00	5:05	651
Common Ar Garage Gut Ofol 1/908 9.50 96 Linear F 912 30.00 5.05 3.08 3.08 1.04 1.05 1.	Gutters & Downspouts	Common Ar	Bldg G Gut	06/01/1996	9.50	60 Linear F	570	30:00	5:05	651
Heat Tape	Gutters & Downspouts	Common Ar	Bldg H Gut	06/01/1996	9.50	60 Linear F	570	30:00	5:05	651
Trigation Common Ar Timer Repl 06/01/2020 \$500.00 1 Allowanc \$500 2:00 1:05 \$517	Gutters & Downspouts	Common Ar	Garage Gut	06/01/1996	9.50	96 Linear F	912	30:00	5:05	1,042
Landscaping - Timers Common Ar Timer Repl 06/01/2020 \$ 500.00 1 Allowanc \$ 500 2:00 1:05 \$ 517 Landscaping - Timers Common Ar Landscape 06/01/2020 \$ 1,500.00 1 Allowanc \$ 1,500 3:00 2:05 \$ 1,592 Contingency - Landscaping Common Ar Landscape 06/01/2019 1,000.00 1 Allowanc \$ 1,500 3:00 2:05 \$ 1,592 Landscaping - Beds & Shrubs Common Ar Bed&Shrub 06/01/2019 1,000.00 1 Allowanc 1,000 2:00 0:05 1,010 Landscaping - Beds & Shrubs Common Ar Bed&Shrub 06/01/2019 1,000.00 3.5 Allowanc 3,500 8:00 6:05 4,100 Trees - Maintenance Common Ar Tree Maintenance Common Ar Tree Repla 06/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Lighting - Exterior Common Ar Lighting Replace 06/01/2021 \$ 165.00 \$ 2 Each \$ 8,580 12:00	Heat Tape	Common Ar	Heat Tape	06/01/2018	3,500.00	1 Allowanc	3,500	6:00	3:05 _	3,808
Landscaping - Timers Common Ar Timer Repl O6/01/2020 \$500.00 1 Allowanc \$500 2:00 1:05 5:17							8,972			11,059
Contingency - Landscaping	_									
Contingency - Landscaping Common Ar Landscape O6/01/2020 \$1,500.00 1 Allowanc \$1,500 3:00 2:05 \$1,592 Landscaping - Beds & Shrubs Common Ar Bed&Shrub O6/01/2019 1,000.00 1 Allowanc 1,000 2:00 0:05 1,010 Common Ar Common Ar Bed&Shrub O6/01/2019 1,000.00 3.5 Allowanc 3,500 8:00 6:05 4,100 Common Ar Tree Maint O6/01/2017 3,000.00 1 Allowanc 3,000 5:00 1:05 3,106 Common Ar Tree Replacement Common Ar Tree Replacement Common Ar Tree Replacement Common Ar Tree Replacement Common Ar Lighting Re O6/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Common Ar Lighting Replacement Common Ar Lighting Replacement Common Ar Lighting Replacement Common Ar Lighting Replacement S,580 12:00 11:05 \$11,374 Common Ar Lighting Replacement S,580 Common Ar Lighting Replacement Common Ar Lighting	Landscaping - Timers	Common Ar	Timer Repl	06/01/2020	\$ 500.00	1 Allowanc		2:00	1:05 _	
Common Ar Landscaping Common Ar Landscape Common Ar Landscape Common Ar Bed&Shrub Common Ar Tree Maint Common Ar Lighting Re Common Ar Bidg A Pain Common Ar Bidg B Pain Common Ar Bidg C Pain Common Ar Bidg C Pain Common Ar Bidg C Pain Common Ar Bidg D Pain Common D Painting Re Common Ar Bidg D Pain Common D Painting Re Common D Painting Painting Re Common D Painting Painting Painting Re Common D Painting Paintin							500			517
Landscaping - Beds & Shrubs Common Ar Bed&Shrub 06/01/2019 1,000.00 1 Allowanc 1,000 2:00 0:05 1,010 Landscaping - Beds & Shrubs Common Ar Bed&Shrub 06/01/2019 1,000.00 3.5 Allowanc 3,500 8:00 6:05 4,100 Trees - Maintenance Common Ar Tree Maint 06/01/2021 750.00 1 Allowanc 3,000 5:00 1:05 3,106 Trees - Replacement Common Ar Tree Repla 06/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Lighting Lighting - Exterior Common Ar Lighting Re 06/01/2020 \$ 165.00 52 Each \$ 8,580 12:00 11:05 \$ 11,374 Lighting - Exterior Common Ar Bldg A Pain 06/01/1996 \$ 3,400.00 1 Allowanc \$ 3,400 26:00 1:05 \$ 3,521 Painting - Building Exterior Common Ar Bldg B Pain 06/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,					4					4
Landscaping - Beds & Shrubs Common Ar Bed & Shrub 06/01/2019 1,000.00 3.5 Allowanc 3,500 8:00 6:05 4,100 Trees - Maintenance Common Ar Tree Maint 06/01/2017 3,000.00 1 Allowanc 3,000 5:00 1:05 3,106 Trees - Replacement Common Ar Tree Repla 06/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Lighting Ughting - Exterior Common Ar Lighting Re 06/01/2020 \$ 165.00 52 Each \$ 8,580 12:00 11:05 \$ 11,374 Painting - Exterior Common Ar Bldg A Pain 06/01/2020 \$ 3,400.00 1 Allowanc \$ 3,400 26:00 1:05 \$ 11,374 Painting - Building Exterior Common Ar Bldg A Pain 06/01/1996 \$ 3,400.00 1 Allowanc \$ 3,400 26:00 1:05 \$ 3,521 Painting - Building Exterior Common Ar Bldg C Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 <td></td>										
Trees - Maintenance Common Ar Tree Maint Tree Maint 06/01/2017 3,000.00 1 Allowanc 3,000 5:00 1:05 3,106 Trees - Replacement Common Ar Tree Repla 06/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Lighting Lighting - Exterior Common Ar Lighting Re 06/01/2020 \$ 165.00 52 Each \$8,580 12:00 11:05 \$11,374 Painting - Building Exterior Common Ar Bldg A Pain 06/01/1996 \$3,400.00 1 Allowanc \$3,400 26:00 1:05 \$3,521 Painting - Building Exterior Common Ar Bldg B Pain 06/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,521 Painting - Building Exterior Common Ar Bldg C Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	· -									
Trees - Replacement Common Ar Tree Repla 06/01/2021 750.00 3 Each 2,250 6:00 6:05 2,636 Lighting Lighting - Exterior Common Ar Lighting Re 06/01/2020 \$ 165.00 52 Each \$8,580 12:00 11:05 \$11,374 Painting - Building Exterior Common Ar Bldg A Pain O6/01/1996 \$3,400.00 1 Allowanc \$3,400 26:00 1:05 \$3,521 Painting - Building Exterior Common Ar Bldg B Pain O6/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 \$3,521 Painting - Building Exterior Common Ar Bldg C Pain O6/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,521 Painting - Building Exterior Common Ar Bldg D Pain O6/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain O6/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609										
Lighting Common Ar Lighting Reversion Common Ar Lighting Reversion \$11,250 \$11,250 \$12,446 Painting - Exterior Common Ar Lighting Reversion \$165.00 \$165.00 \$2 Each \$8,580 \$12:00 \$11:05 \$11,374 Painting - Building Exterior Common Ar Bldg A Pain \$06/01/1996 \$3,400.00 \$3,400 \$3,400 \$26:00 \$1:05 \$3,521 Painting - Building Exterior Common Ar Bldg A Pain \$06/01/1996 \$3,400.00 \$1 Allowanc \$3,400 \$26:00 \$1:05 \$3,521 Painting - Building Exterior Common Ar Bldg C Pain \$06/01/1996 \$3,400.00 \$1 Allowanc \$3,400 \$26:00 \$1:05 \$3,521 Painting - Building Exterior Common Ar Bldg C Pain \$06/01/1996 \$3,400.00 \$1 Allowanc \$3,400 \$2:00 \$2:05 \$3,600 Painting - Building Exterior Common Ar Bldg D Pain \$06/01/1996 \$3,400.00 \$3,400 \$3,400 \$2:00 \$2:05 \$3,600										
Lighting Lighting - Exterior Common Ar Lighting Re Painting - Building Exterior Common Ar Common Ar Painting - Building Exterior Lighting Re Paint Re Painting - Building Exterior Lighting Re Paint Re Painting - Building Exterior Common Ar Common Ar Bldg B Pain Paint Re Painting - Building Exterior Sa,580 Pain Re Paint Re P	Trees - Replacement	Common Ar	Tree Repla	06/01/2021	750.00	3 Each		6:00	6:05	
Lighting - Exterior Common Ar Lighting Re Ughting Re Ughting Re Ughting Re Ughting - Exterior 06/01/2020 \$ 165.00 52 Each Sach Sach Sach Sach Sach Sach Sach S							11,250			12,446
8,580 11,374 Painting - Building Exterior Common Ar Bldg A Pain 06/01/1996 \$3,400.00 1 Allowanc \$3,400 26:00 1:05 \$3,521 Painting - Building Exterior Common Ar Bldg B Pain 06/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,521 Painting - Building Exterior Common Ar Bldg C Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	Lighting									
Painting Painting - Building Exterior Common Ar Bldg A Pain 06/01/1996 \$3,400.00 1 Allowanc \$3,400 26:00 1:05 \$3,521 Painting - Building Exterior Common Ar Bldg B Pain 06/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,521 Painting - Building Exterior Common Ar Bldg C Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	Lighting - Exterior	Common Ar	Lighting Re	06/01/2020	\$ 165.00	52 Each	\$ 8,580	12:00	11:05	\$ 11,374
Painting - Building Exterior Common Ar Painting - Building Exterior Edg A Pain Painting - Building Exterior 06/01/1996 \$ 3,400.00 1 Allowanc \$ 3,400 26:00 1:05 \$ 3,521 Painting - Building Exterior Common Ar Common Ar Bldg C Pain Painting - Building Exterior Common Ar Bldg C Pain Painting - Building Exterior 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain Painting - Building Exterior 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609							8,580			11,374
Painting - Building Exterior Common Ar Painting - Building Exterior Edg B Pain Painting - Building Exterior 06/01/1996 3,400.00 1 Allowanc 3,400 26:00 1:05 3,521 Painting - Building Exterior Common Ar Common Ar Bldg C Pain Painting - Building Exterior Bldg D Pain Painting - Building Exterior 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	Painting									
Painting - Building Exterior Common Ar Bldg C Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609 Painting - Building Exterior Common Ar Bldg D Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	Painting - Building Exterior	Common Ar	Bldg A Pain	06/01/1996	\$ 3,400.00	1 Allowanc	\$ 3,400	26:00	1:05	\$ 3,521
Painting - Building Exterior Common Ar Bldg D Pain 06/01/1996 3,400.00 1 Allowanc 3,400 27:00 2:05 3,609	Painting - Building Exterior	Common Ar	Bldg B Pain	06/01/1996	3,400.00	1 Allowanc	3,400	26:00	1:05	3,521
	Painting - Building Exterior	Common Ar	Bldg C Pain	06/01/1996	3,400.00	1 Allowanc	3,400	27:00	2:05	3,609
Painting - Building Exterior Common Ar Bldg E Pain 06/01/1996 3,400.00 1 Allowanc 3,400 28:00 3:05 3,699		Common Ar	_	06/01/1996	3,400.00	1 Allowanc	3,400	27:00	2:05	3,609
	Painting - Building Exterior	Common Ar	Bldg E Pain	06/01/1996	3,400.00	1 Allowanc	3,400	28:00	3:05	3,699



Analysis Date - January 1, 2021

Page 27

Painting - Building Exterior Common Ar Bldg F Pain 06/01/1996 3,400.00 1 Allowanc 3,400 28:00 3:05 3,699



Analysis Date - January 1, 2021

Page 28

Item Parameters - Detail

Subcategory			Service				Adj	Rem	
Reserve Item	Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Future Cost
					- Quantity				
Dainting Duilding Eutories	Common Ar	Dida C Dain	06/01/1006	ć 2 400 00	1 Allowanc	¢ 2 400	29:00	4.05	¢ 2 701
Painting - Building Exterior	Common Ar Common Ar	Bldg G Pain	06/01/1996 06/01/1996	\$ 3,400.00 3,400.00	1 Allowanc	\$ 3,400 3,400	29:00	4:05 4:05	\$ 3,791 3,791
Painting - Building Exterior Painting - Building Exterior	Common Ar	Bldg H Pain Garage Pai	06/01/1996	3,400.00	0.5 Allowanc	1,700	30:00	5:05	1,943
Painting - Building Exterior	Common Ar	Garage Pai	06/01/1996	3,400.00	0.5 Allowanc	1,700	30:00	5:05	1,943
Fairting - Building Exterior	Common Ai	Garage Fai	00/01/1990	3,400.00	0.5 Allowalic		30.00	J.05 _	
Pavina						30,600			33,128
Paving		A 1 110	05/04/4005	64.00	4.44611	64.446	26.00	4.05	64455
Asphalt - Crackfill	Common Ar	AsphaltCra	06/01/1996	\$ 1.00	1,116 Linear F	\$ 1,116	26:00	1:05	\$ 1,155
Asphalt - Overlay	Common Ar	Asphalt Ov	06/01/1996	2.00	7,440 Square F	14,880	35:00	10:05	19,244
Asphalt - Repairs	Common Ar	Asphalt Re	06/01/1996	4.00	744 Square F	2,976	26:00	1:05	3,081
Asphalt - Sealing	Common Ar	Asphalt Se	06/01/1996	0.25	7,440 Square F	1,860	26:00	1:05	1,926
Pavers - Brick	Common Ar	Pavers Rep	06/01/2016	7.50	64 Square F	480	20:00	15:05 _	702
						21,312			26,110
Reserve Study									
Reserve Study Update	Common Ar	Full Study	06/01/2021	\$ 2,940.00	1 Lump Sum	\$ 2,940	5:00	5:05	\$ 3,360
Reserve Study Update	Common Ar	FinancialU	06/01/2021	2,940.00	0.15 Lump Sum	441	1:00	1:05	456
Reserve Study Update	Common Ar	FinancialU	06/01/2021		0.15 Lump Sum	441	2:00	2:05	468
Reserve Study Update	Common Ar	FinancialU	06/01/2021		0.15 Lump Sum	441	3:00	3:05	479
Reserve Study Update	Common Ar	FinancialU	06/01/2021	2,940.00	0.15 Lump Sum	441	4:00	4:05 _	491
						4,704			5,257
Roofing									
Roofing - 30-yr Compositional	Common Ar	Bldg A Roo	06/01/1996	\$ 650.00	42 Squares	\$ 27,300	30:00	5:05	\$ 31,206
Roofing - 30-yr Compositional	Common Ar	Bldg B Roof	06/01/2019	650.00	35 Squares	22,750	30:00	28:05	45,889
Roofing - 30-yr Compositional	Common Ar	Bldg C Roof	06/01/1996	650.00	35 Squares	22,750	30:00	5:05	26,005
Roofing - 30-yr Compositional	Common Ar	Bldg D Roo	06/01/1996	650.00	42 Squares	27,300	30:00	5:05	31,206
Roofing - 30-yr Compositional	Common Ar	Bldg E Roof	06/01/2019	650.00	35 Squares	22,750	30:00	28:05	45,889
Roofing - 30-yr Compositional	Common Ar	Bldg F Roof	06/01/1996	650.00	35 Squares	22,750	26:00	1:05	23,559
Roofing - 30-yr Compositional	Common Ar	Bldg G Roo	06/01/1996	650.00	35 Squares	22,750	30:00	5:05	26,005
Roofing - 30-yr Compositional	Common Ar	Bldg H Roo	06/01/1996	650.00	35 Squares	22,750	25:00	0:05	22,985
Roofing - 30-yr Compositional	Common Ar	Garage Ro	06/01/1996	650.00	31 Squares	20,150	30:00	5:05	23,033
						211,250			275,783
Shade Structures									
Pavilion - Maintenance	Common Ar	Pavilion Re	06/01/2016	\$ 1,600.00	1 Allowanc	\$ 1,600	10:00	5:05	\$ 1,828
					•	1,600		_	1,828
Staining									
Staining - Exterior	Common Ar	Timber Stai	06/01/2014	\$ 120.00	26 Allowanc	\$ 3,120	8:00	1:05	\$ 3,231
			,,	,		3,120			3,231
Structural Repairs						3,120			3,231
•	Common Ar	Building Mi	06/01/2017	\$ 2,200.00	1 Allowanc	\$ 2,200	7:00	3:05	\$ 2,393
Contingency - Building Exterior Siding & Trim	Common Ar	_		48,000.00	1 Allowanc				63,631
Siding & Trim	Common Ar	Bldg A Sidi Bldg B Sidi	06/01/1996 06/01/1996	48,000.00	1 Allowanc	48,000 48,000	36:00 37:00	11:05 12:05	
•		-							65,222
Siding & Trim Siding & Trim	Common Ar Common Ar	Bldg C Sidi Bldg D Sidi	06/01/1996 06/01/1996	48,000.00 48,000.00	1 Allowanc 1 Allowanc	48,000 48,000	38:00 39:00	13:05 14:05	66,852 68,524
Siding & Trim	Common Ar	Bldg E Sidi	06/01/1996	48,000.00	1 Allowanc	48,000	40:00	15:05	70,237
Siding & Trim	Common Ar	Bldg F Sidin	06/01/1996	48,000.00		48,000	41:00	16:05	
Siding & Trim	Common Ar	Bldg G Sidi	06/01/1996	48,000.00	1 Allowanc 1 Allowanc	48,000	42:00	17:05	71,993 73,793
Siding & Trim	Common Ar	Bldg H Sidi	06/01/1996	48,000.00	1 Allowanc	48,000	43:00	18:05	75,637
Siding & Trim	Common Ar	Garage Sidi	06/01/1996	48,000.00	0.35 Allowanc	16,800	44:00	19:05	27,135
Siding & Trim	Common Ar	Garage Sidi	06/01/1996	48,000.00	0.35 Allowanc	16,800	44:00	19:05	27,135
Jiumg & Tim	Common Al	Jarage Jiul	30/01/1330	+0,000.00	5.55 Allowalic	10,600	77.00	15.05	27,133



Analysis Date - January 1, 2021

									Page 29
Siding & Trim	Common Ar	Siding Mtn	06/01/2018	48,000.00	0.1 Allowanc	4,800	5:00	2:05	5,095



Analysis Date - January 1, 2021

Page 30

Item Parameters - Detail

Subcategory			Service				Adj	Rem	
Reserve Item	Location	Desc.	Date	Basis Cost	Quantity	Current Cost	Life	Life	Future Cost
Soffits & Fascia	Common Ar	Soffit Repai	06/01/1996	\$ 2,500.00	1 Allowanc	\$ 2,500	28:00	3:05	\$ 2,720
						427,100		_	620,371
Utility Infrastructure									
Utility Infrastructure	Common Ar	Utility Mai	06/01/2013	\$ 6,500.00	1 Allowanc	\$ 6,500	15:00	7:05	\$ 7,806
						6,500		_	7,806
Windows									
Windows	Common Ar	Bldg A Win	06/01/1996	\$ 350.00	15 Each	\$ 5,250	36:00	11:05	\$ 6,959
Windows	Common Ar	Bldg B Win	06/01/1996	350.00	15 Each	5,250	37:00	12:05	7,133
Windows	Common Ar	Bldg C Win	06/01/1996	350.00	15 Each	5,250	38:00	13:05	7,312
Windows	Common Ar	Bldg D Win	06/01/1996	350.00	15 Each	5,250	39:00	14:05	7,494
Windows	Common Ar	Bldg E Win	06/01/1996	350.00	15 Each	5,250	40:00	15:05	7,682
Windows	Common Ar	Bldg F Win	06/01/1996	350.00	15 Each	5,250	41:00	16:05	7,874
Windows	Common Ar	Bldg G Win	06/01/1996	350.00	15 Each	5,250	42:00	17:05	8,071
Windows	Common Ar	Bldg H Win	06/01/1996	350.00	15 Each	5,250	43:00	18:05	8,272
						42,000			60,800
						854,638		_	1,157,408
								=	

Analysis Date - January 1, 2021



Page 31

Item Parameters - Full Detail

Asphalt - Crackfill

Item Numbe	er	1			Me	asurement Basis		Linear F
Туре		Common Are	a		Esti	mated Useful Life		3 Years
Category		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		1.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	AsphaltCrackfi	06/01/1996	06/01/2022	1:05	26:00	1,116	1,116.00	1,155.73
							1,116.00	1,155.73
Comments								

This component funds periodic crackfill of the asphalt as needed. It includes blowing out and filling cracks with hot rubber. Proper sealing will help mitigate water infiltration which can undermine the asphalt. This component runs in conjunction with *Asphalt - Repairs* and with *Asphalt - Sealing*. The Quantity (in Linear Feet) is calculated at **15**% of the total asphalt surface area. At the time of this study, the asphalt is in rough condition and need of an aggressive maintenance schedule. Measurements are approximate by NSR.





Analysis Date - January 1, 2021



Page 32

Item Parameters - Full Detail

Asphalt - Overlay

Item Number Type Category		2 Common Area			Me	asurement Basis		Square F
					Esti	mated Useful Life		35 Years
		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		2.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Asphalt Overla	06/01/1996	06/01/2031	10:05	35:00	7,440	14,880.00	19,244.64
							14,880.00	19,244.64
Comments								

This component funds grinding out approx. 2" of asphalt top coat in the roadways and resurfacing the area with an asphalt "overlay" in lieu of full replacement. This component may extend beyond the scope of this study if regular crackfill and seal coating are followed, however, it was included as it represents a significant future expense. This ensures funds are available if the asphalt should need overlayment at the end of its Useful Life. The Quantity is calculated at **100%** of the total asphalt surface area. At the time of this study, the asphalt is in rough condition and need of an aggressive maintenance schedule. For this reason overlay is listed early in the study. Measurements are approximate by NSR.





Analysis Date - January 1, 2021



Page 33

Item Parameters - Full Detail

Asphalt - Repairs

	F							
Item Numbe	er	3			Me	asurement Basis		Square F
Type Category		Common Area			Esti	mated Useful Life		6 Years
		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		4.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Asphalt Repair	06/01/1996	06/01/2022	1:05	26:00	744	2,976.00	3,081.95
							2,976.00	3,081.95
Comments								

This component includes minor dig and fill of potholes or failing asphalt in the roadways. This component ensures that ongoing funds are available for repairs and mitigation when needed. This component Quantity is calculated at 10% of the total asphalt surface area. Time will dictate if the Quantity needs to be adjusted. This component runs in conjunction with *Asphalt - Crackfill* and with *Asphalt - Sealing*. At the time of this study, the asphalt is in rough condition and need of an aggressive maintenance schedule. For this reason repairs are listed early in the study, particularly to repair the potholes on the north side. Measurements are approximate by NSR.





Analysis Date - January 1, 2021



Page 34

Item Parameters - Full Detail

Asphalt - Sealing

Item Number Type Category		4 Common Area Exterior - Landscape & Grounds			Me	asurement Basis		Square I	
					Esti	mated Useful Life		6 Years	
					Bas	sis Cost		0.25	
Tracking		Logistical							
Method		Adjusted							
		Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost	
Common Area	Asphalt Seal	06/01/1996	06/01/2022	1:05	26:00	7,440	1,860.00	1,926.22	
							1,860.00	1,926.22	
Comments									

This component funds application of two coats of an asphalt polymer emulsion product to the asphalt roadways throughout the community. A Seal Coat will help ensure the asphalt reaches its full Useful Life. This component runs in conjunction with *Asphalt - Crackfill* and *Asphalt - Repairs*. At the time of this study, the asphalt is in rough condition and need of an aggressive maintenance schedule. Measurements are approximate by NSR.





Garland Meadows Homeowners' Association, In Analysis Date - January 1, 2021





Page 35

Item Parameters - Full Detail

Concrete Repair

Item Number Type Category		8 Common Area Exterior - Landscape & Grounds			Measurement Basis Estimated Useful Life			Allowanc 8 Years
					Bas	sis Cost		2,000.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Driveway Rep	06/01/1996	06/01/2022	1:05	26:00	1	2,000.00	2,071.20
Common Area	Walkways Rep	06/01/2014	06/01/2024	3:05	10:00	0.5	1,000.00	1,088.03
							3,000.00	3,159.23
Comments								

This component funds lifting, patching, grinding or general repairs to concrete throughout the community. This component ensures funds are available on a periodic basis to repair trip hazards. The Useful Life (UL) of concrete may extend beyond the scope of this study. Due to the volume of common area concrete, it is requisite that funds be available for maintenance and repairs that fall outside of the operating budget. This is an allowance only. Time will dictate if more or less is needed as weather and landscaping continue to have an impact on the life of the concrete. At the time of this study, NSR found many damaged or failing concrete. For this reason the allowance was increased to fund ongoing repairs. A second line item was included to outline walkway maintenance, albeit at a different rotational UL and Quantity. *U-Channels & Curbing* outlined in a separate component.







NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 36







Analysis Date - January 1, 2021



Page 37

Item Parameters - Full Detail

Contingency - Building Exterior

Item Numbe	er	5			Me	easurement Basis		Allowanc
Туре		Common Are	a		Esti	imated Useful Life		7 Years
Category		Exterior - Ma	terials		Bas	sis Cost		2,200.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Building Misc	06/01/2017	06/01/2024	3:05	7:00	1	2,200.00	2,393.66
							2,200.00	2,393.66
Comments								

This component provides ongoing funds as a contingency to supplement the operating budget as it relates to miscellaneous building repairs and maintenance not provided for in another component, including but not limited to address numbers, caulking, vents and louvers, window repair and more as directed by BOD. The funding here is intended to be an allowance only, which supplements the budget against unplanned and/or unexpected repairs.







Analysis Date - January 1, 2021



Page 38

Item Parameters - Full Detail

Contingency - Landscaping

Item Numbe	er	18 Common Are	a			asurement Basis mated Useful Life		Allowanc 3 Years
Category		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		1,500.00
Tracking		Logistical	•					
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Landscape Mis	06/01/2020	06/01/2023	2:05	3:00	1	1,500.00	1,592.24
							1,500.00	1,592.24
Comments								

This component provides ongoing funds as a contingency to supplement the operating budget as it relates to miscellaneous landscaping needs not provided for in another component, including but not limited to backflow preventers, bark replenishment, covers and grates, pet station(s), sprinkler rehab, valves and boxes and more as directed by BOD. The funding here is intended to be an allowance only, which supplements the budget against unplanned and/or unexpected needs.







NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 39

Item Parameters - Full Detail

Doors - Exterior

Item Numbe	er	12 Common Are	a			asurement Basis		Each 25 Years
		Exterior - Ma	-			iis Cost		275.00
Category Tracking Method		Logistical		Das	iis Cost		273.00	
ivietnoa		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Entry Door Re	06/01/1996	06/01/2026	5:05	30:00	26	7,150.00	8,173.23
Common Area	Garage Doors	06/01/1996	06/01/2026	5:05	30:00	8	2,200.00	2,514.84
							9,350.00	10,688.07
Comments								

This component replaces the exterior insulated fiberlgass doors that service both the entry to the units as well as the garage man door exits. Counts are approximate by NSR.





NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 40

Item Parameters - Full Detail

Doors - Sliding Glass

Item Numbe	er	13			Me	asurement Basis		Each
Туре		Common Are	a		Esti	mated Useful Life		25 Years
Category		Exterior - Ma	terials		Bas	sis Cost		850.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Glass Door Re	06/01/1996	06/01/2024	3:05	28:00	52	44,200.00	48,090.82
							44,200.00	48,090.82
Comments								

This component replaces the exterior sliding glass doors. Counts are approximate by NSR.



Analysis Date - January 1, 2021



Page 41

Item Parameters - Full Detail

Furnishings & Décor

Item Numbe	er	14			Me	asurement Basis		Allowanc
Туре		Common Are	a		Esti	mated Useful Life		8 Years
Category		Interior - Mat	erials		Bas	sis Cost		2,500.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Pavilion Furnit	06/01/2015	06/01/2023	2:05	8:00	1	2,500.00	2,653.73
							2,500.00	2,653.73
Comments								

This component provides an allowance which replaces, in aggregate, the decor and furniture and other miscellaneous decor pieces. This is an allowance only.





Northstar Reserves

Analysis Date - January 1, 2021

Page 42

Item Parameters - Full Detail

Garage Door - Metal, Single Bay

Item Numbe	er	15			Me	asurement Basis		Each
Туре		Common Are	a		Esti	mated Useful Life		35 Years
Category		Exterior - Equ	ipment		Bas	sis Cost		650.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	GarageDoorRe	06/01/1996	06/01/2031	10:05	35:00	26	16,900.00	21,857.16
							16,900.00	21,857.16
Comments								

This component replaces a metal single-bay garage door. Counts are approximate by NSR. Openers are excluded.





Analysis Date - January 1, 2021



Page 43

Item Parameters - Full Detail

Gutters & Downspouts

Item Number	16	Measurement Basis	Linear F
Туре	Common Area	Estimated Useful Life	30 Years
Category	Exterior - Landscape & Grounds	Basis Cost	9.50
Tracking	Logistical		
Method	Adjusted		

		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bldg A Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Bldg B Gutters	06/01/2019	06/01/2049	28:05	30:00	60	570.00	1,149.77
Common Area	Bldg C Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Bldg D Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Bldg E Gutters	06/01/2019	06/01/2049	28:05	30:00	60	570.00	1,149.77
Common Area	Bldg F Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Bldg G Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Bldg H Gutters	06/01/1996	06/01/2026	5:05	30:00	60	570.00	651.57
Common Area	Garage Gutter	06/01/1996	06/01/2026	5:05	30:00	96	912.00	1,042.52
							5,472.00	7,251.48
Comments								

This component replaces the gutters and downspouts, as needed, throughout the community. Ongoing maintenance and inspections of the gutters will ensure ice build up and trees don't damage the gutters long-term. This component runs in conjunction with *Roofing* replacement. Is is assumed that minor and periodic repairs will fund from either the operating budget or *Contingency - Building Exterior*. Measurements are approximate by NSR.





Analysis Date - January 1, 2021



Page 44

Item Parameters - Full Detail

Heat Tape

Item Numbe	er	17			Me	asurement Basis		Allowanc
Туре		Common Are	a		Esti	mated Useful Life		6 Years
Category		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost	3,500.00	
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Heat Tape	06/01/2018	06/01/2024	3:05	6:00	1	3,500.00	3,808.10
							3,500.00	3,808.10
Comments								

This component replaces the gutter heat tape system. Regular usage and management of these funds promotes a full Useful Life of the gutters and downspouts. This is an ongoing allowance replace the heat tape.





Analysis Date - January 1, 2021



Page 45

Item Parameters - Full Detail

Landscaping - Beds & Shrubs

Item Numbe	er	19 Common Are	a			easurement Basis		Allowanc 2 Years
Category		Exterior - Lan	- dscape & Gro	unds		sis Cost		1,000.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bed&Shrub Re	06/01/2019	06/01/2021	0:05	2:00	1	1,000.00	1,010.34
Common Area	Bed&Shrub Re	06/01/2019	06/01/2027	6:05	8:00	3.5	3,500.00	4,100.90
							4,500.00	5,111.24
Comments								

This is an allowance to rehab the flower beds, shrubs and water management within the landscaped areas. Some small rehab is needed every year to keep the community in top aesthetical condition and to prevent additional problems from the overgrowth of current shrubbery. Time and weather will also continue to have a direct impact on the health and thereby aesthetics of the flower beds and shrubbery. An additional line item is included periodically to ensure funds are available for more significant changes.





NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 46

Item Parameters - Full Detail

Landscaping - Timers

Item Numbe	er	20			Me	asurement Basis		Allowanc
Туре		Common Are	a		Esti	mated Useful Life		2 Years
Category		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		500.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Timer Replace	06/01/2020	06/01/2022	1:05	2:00	1	500.00	517.80
							500.00	517.80
Comments								

This component systemically and regularly funds the replacement of several landscape timers in the common area landscaping. It is unlikely that all timers will fail simultaneously. Therefore, funding is provided here in order to replace those failing, or those oldest, prior to their eventual failure and on a regular basis.



NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 47

Item Parameters - Full Detail

Lighting - Exterior

Item Numbe	er	24			Me	asurement Basis		Each
Туре		Common Are	a		Esti	mated Useful Life		12 Years
Category		Exterior - Equipment			Bas	sis Cost		165.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Lighting Repla	06/01/2020	06/01/2032	11:05	12:00	52	8,580.00	11,374.13
							8,580.00	11,374.13
Comments								

This component replaces the exterior lighting fixtures found in the common areas of the community. This is an aggregate replacement that aligns with *Painting*. Counts are approximate by NSR.



Analysis Date - January 1, 2021



Page 48

Item Parameters - Full Detail

Painting - Building Exterior

Comments

Adjusted

Item Number	25	Measurement Basis	Allowanc
item Number	23	Wicasurement Dasis	Allowalic
Туре	Common Area	Estimated Useful Life	10 Years
Category	Exterior - Materials	Basis Cost	3,400.00
Tracking	Logistical		
Method	Adjusted		

		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bldg A Paint	06/01/1996	06/01/2022	1:05	26:00	1	3,400.00	3,521.04
Common Area	Bldg B Paint	06/01/1996	06/01/2022	1:05	26:00	1	3,400.00	3,521.04
Common Area	Bldg C Paint	06/01/1996	06/01/2023	2:05	27:00	1	3,400.00	3,609.07
Common Area	Bldg D Paint	06/01/1996	06/01/2023	2:05	27:00	1	3,400.00	3,609.07
Common Area	Bldg E Paint	06/01/1996	06/01/2024	3:05	28:00	1	3,400.00	3,699.29
Common Area	Bldg F Paint	06/01/1996	06/01/2024	3:05	28:00	1	3,400.00	3,699.29
Common Area	Bldg G Paint	06/01/1996	06/01/2025	4:05	29:00	1	3,400.00	3,791.78
Common Area	Bldg H Paint	06/01/1996	06/01/2025	4:05	29:00	1	3,400.00	3,791.78
Common Area	Garage Paint	06/01/1996	06/01/2026	5:05	30:00	0.5	1,700.00	1,943.29
Common Area	Garage Paint	06/01/1996	06/01/2026	5:05	30:00	0.5	1,700.00	1,943.29
							30,600.00	33,128.94

This component funds an allowance for painting the building exterior with a high quality exterior paint. Time and wear will dictate if this allowance needs to be adjusted. At the time of this study there were several area observed where either a hole was present for the intrusion of water or the siding has taken on water and has swollen. NSR was informed that painting has not been done since inception. For these reasons this component is listed early in the study.





NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 49

Item Parameters - Full Detail

Pavers - Brick

Item Number21TypeCommon Are				Me	asurement Basis		Square F	
		Common Are	a		Esti	mated Useful Life		20 Years
Category		Exterior - Landscape & Grounds		Bas	sis Cost	7.50		
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Pavers Replac	06/01/2016	06/01/2036	15:05	20:00	64	480.00	702.37
							480.00	702.37
Comments								

This component replaces, in aggregate, the brick pavers. Ongoing maintenance should fund via the operating budget. Measurements are approximate by NSR.



Analysis Date - January 1, 2021



Page 50

Item Parameters - Full Detail

Pavilion - Maintenance

Item Number		26			Me	asurement Basis		Allowanc
Туре		Common Are	a		Esti	mated Useful Life		6 Years
Category		Exterior - Lan	dscape & Gro	unds	Bas	is Cost		1,600.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Pavilion Repair	06/01/2016	06/01/2026	5:05	10:00	1	1,600.00	1,828.97
							1,600.00	1,828.97
Comments								

This component is an allowance to aid in the maintenance and upkeep of the pavilion located in the common area. The Basis Cost includes, but is not limited to, rain gutters, downspouts, stone work, trim repair, roof repair, etc. This component excludes staining of trim and timber work as it is provided for in a separate component. The structure may extend beyond the scope of this study. Regular inspection and maintenance will promote a full Useful Life.







NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 51

Item Parameters - Full Detail

Reserve S	Study L	Jpdate
-----------	---------	--------

Item Number	27			Measurement Basis		Lump Sum
Туре	Common Area	ì		Estimated Useful Life		5 Years
Category	Reserve Study	,		Basis Cost		2,940.00
Tracking	Logistical					
Method	Adjusted					
	Service	Replace	Rem	Adj	Current	Future

		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Full Study	06/01/2021	06/01/2026	5:05	5:00	1	2,940.00	3,360.74
Common Area	FinancialUpda	06/01/2021	06/01/2022	1:05	1:00	0.15	441.00	456.70
Common Area	FinancialUpda	06/01/2021	06/01/2023	2:05	2:00	0.15	441.00	468.12
Common Area	FinancialUpda	06/01/2021	06/01/2024	3:05	3:00	0.15	441.00	479.82
Common Area	FinancialUpda	06/01/2021	06/01/2025	4:05	4:00	0.15	441.00	491.82
							4,704.00	5,257.20

Comments

This is an alternating line item for an updated Reserve Study. The reserve costs for a 5-year full study, which includes a visual observation of the accessible reserve components, is alternately interspersed with an annual financial update.



Analysis Date - January 1, 2021



Page 52

Item Parameters - Full Detail

Roofing - 30-yr Compositional

Item Number	28	Measurement Basis	Squares
Туре	Common Area	Estimated Useful Life	30 Years
Category	Exterior - Materials	Basis Cost	650.00
Tracking	Logistical		
Method	Adjusted		


		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bldg A Roof	06/01/1996	06/01/2026	5:05	30:00	42	27,300.00	31,206.87
Common Area	Bldg B Roof	06/01/2019	06/01/2049	28:05	30:00	35	22,750.00	45,889.98
Common Area	Bldg C Roof	06/01/1996	06/01/2026	5:05	30:00	35	22,750.00	26,005.73
Common Area	Bldg D Roof	06/01/1996	06/01/2026	5:05	30:00	42	27,300.00	31,206.87
Common Area	Bldg E Roof	06/01/2019	06/01/2049	28:05	30:00	35	22,750.00	45,889.98
Common Area	Bldg F Roof	06/01/1996	06/01/2022	1:05	26:00	35	22,750.00	23,559.91
Common Area	Bldg G Roof	06/01/1996	06/01/2026	5:05	30:00	35	22,750.00	26,005.73
Common Area	Bldg H Roof	06/01/1996	06/01/2021	0:05	25:00	35	22,750.00	22,985.27
Common Area	Garage Roofs	06/01/1996	06/01/2026	5:05	30:00	31	20,150.00	23,033.64
							211,250.00	275,783.98

Comments

This component replaces the existing roofing with a 30-year dimensional composition roofing product such as GAF Timberline HD Shingles or equal. Ongoing inspections and maintenance will ensure the roof achieves its full Useful Life. Additional funding was included herein to fund the replacement of soffit and fascia where necessary. Counts are approximate by NSR.







NORTHSTAR RESERVES

Page 53

73,793.01

75,637.84

27,135.07

27,135.07

5,095.15

615,257.30

Item Parameters - Full Detail

•	: 4	:	- 0	Tri	
•	ın	ınc	, x.	ırı	m

Item Numbe	Item Number				Me	Measurement Basis			
Туре		Common Are	a		Esti	mated Useful Life		40 Years	
Category		Exterior - Mat	terials		Bas		48,000.00		
Tracking		Logistical							
Method		Adjusted							
		Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost	
Common Area	Bldg A Siding	06/01/1996	06/01/2032	11:05	36:00	1	48,000.00	63,631.48	
Common Area	Bldg B Siding	06/01/1996	06/01/2033	12:05	37:00	1	48,000.00	65,222.27	
Common Area	Bldg C Siding	06/01/1996	06/01/2034	13:05	38:00	1	48,000.00	66,852.83	
Common Area	Bldg D Siding	06/01/1996	06/01/2035	14:05	39:00	1	48,000.00	68,524.15	
Common Area	Bldg E Siding	06/01/1996	06/01/2036	15:05	40:00	1	48,000.00	70,237.25	
Common Area	Bldg F Siding	06/01/1996	06/01/2037	16:05	41:00	1	48,000.00	71,993.18	

17:05

18:05

19:05

19:05

2:05

42:00

43:00

44:00

44:00

5:00

1

1

0.35

0.35

0.1

48,000.00

48,000.00

16,800.00

16,800.00

4,800.00

422,400.00

Comments

Common Area

Common Area Bldg G Siding

Common Area Bldg H Siding

Common Area Garage Siding

Common Area Siding Mtnc

Garage Siding

06/01/1996

06/01/1996

06/01/1996

06/01/1996

06/01/2018

06/01/2038

06/01/2039

06/01/2040

06/01/2040

06/01/2023

This component funds the replacement of the exterior siding and trim, building by building. The last line item is for periodic repair of the siding and exterior trim on a shortened periodic basis. Regular inspections and repair of siding will promote its full Useful Life. At the time of this study there were several areas observed where either a hole was present for the intrusion of water or the siding has taken on water and has swollen. NSR was informed that painting has not been done since inception. The allowance is an estimate based on like-kind communities. NSR recommends bids from vendors prior to full funding of this component.

NORTHSTAR RESERVES

Analysis Date - January 1, 2021

Page 54



Analysis Date - January 1, 2021




Page 55

Item Parameters - Full Detail

Soffits & Fascia

3011113 & 1 a.	Jeiu							
Item Numbe					Me		Allowanc	
Туре				Esti		5 Years		
Category		Exterior - Ma	terials	Basis Cost				2,500.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Soffit Repair	06/01/1996	06/01/2024	3:05	28:00	1	2,500.00	2,720.07
							2,500.00	2,720.07
Comments								

This component is an ongoing allowance for the repair and replacement of damage, sagging or failing soffits and fascia. Replacement funding is included as part of the *Roofing* component.









Analysis Date - January 1, 2021



Page 56

Item Parameters - Full Detail

Staining - Exterior

Item Numbe	er	30			Measurement Basis			Allowanc
Type Category		Common Are	a		Estimated Useful Life			8 Years
		Exterior - Ma	terials		Bas	sis Cost		120.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Timber Stainin	06/01/2014	06/01/2022	1:05	8:00	26	3,120.00	3,231.07
							3,120.00	3,231.07
Comments								

This component stains the exterior wood components throughout the community. Regular staining and care of the timberwork promotes a full Useful Life. Regular and consistent staining will be **essential** to maintain the timber beyond the scope of this study and prevent full replacement.





Analysis Date - January 1, 2021



Page 57

Item Parameters - Full Detail

Trees - Maintenance

Item Number Type Category		22 Common Area Exterior - Landscape & Grounds			Measurement Basis Estimated Useful Life			Allowanc 5 Years
					Tracking		Logistical	
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Tree Maintnc	06/01/2017	06/01/2022	1:05	5:00	1	3,000.00	3,106.80
							3,000.00	3,106.80
Comments	Tree Walltine	00,01,2017	00,01,2022	1.03	3.00	<u> </u>		-

This allowance funds structural pruning and removal of trees as needed to enhance the landscaping and to avoid branch and root damage to nearby objects and structures. Time will dictate if the Basis Cost and Useful Life will need to be adjusted as trees continue to mature.







Analysis Date - January 1, 2021



Page 58

Item Parameters - Full Detail

Trees - Replacement

Item Number Type Category		23 Common Area			Me	asurement Basis		Each	
					Esti	mated Useful Life		8 Years	
		Exterior - Lan	dscape & Gro	unds	Bas	sis Cost		750.00	
Tracking		Logistical							
Method		Adjusted							
		Service	Replace	Rem	Adj		Current	Future	
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost	
Common Area	Tree Replace	06/01/2021	06/01/2027	6:05	6:00	3	2,250.00	2,636.29	
							2,250.00	2,636.29	
Comments									

This component funds the removal and replacement of trees as needed to enhance the landscaping and to avoid branch and root damage to buildings, streets and walkways. Time will dictate if the Basis Cost needs to be adjusted as trees continue to mature. Counts are approximate by NSR.







Analysis Date - January 1, 2021



Page 59

Item Parameters - Full Detail

U-Channel & Curbing

Item Number Type Category		10			Measurement Basis			Allowanc
		Common Area			Esti	mated Useful Life		3 Years
		Exterior - Lan	dscape & Gro	unds	Bas	is Cost		1,200.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	U-ChannelRep	06/01/2010	06/01/2022	1:05	12:00	1	1,200.00	1,242.72
							1,200.00	1,242.72


Comments

This component is an allowance which funds the repair and replacement of the U-Channels and gutter curbing throughout the community. Failure to maintain the U-channels may result in improper water mitigation and damage, undermining surrounding asphalt and concrete through an increase of water flow "washout" of subsurface area. This component funds lifting, patching, grinding or general repairs to said concrete. Time will dictate if more or less is needed as weather and landscaping continue to have an impact on the life of the concrete. At the time of this study, NSR found many damaged or failing concrete. For this reason the allowance was increased to fund ongoing repairs. Sidewalk *Concrete* listed in a separate component.











Page 60

Item Parameters - Full Detail

Utility Infrastructure

Item Numbe	er	32			Measurement Basis			Allowanc
Туре		Common Are	a		Esti	mated Useful Life		10 Years
Category		Exterior - Mat	terials		Bas	sis Cost		6,500.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Utility Maintn	06/01/2013	06/01/2028	7:05	15:00	1	6,500.00	7,806.36
							6,500.00	7,806.36
Comments								

This component provides funds to maintain and repair the utility infrastructure. Having some funds budgeted for unexpected infrastructure needs is fiscally prudent. Time will dictate if this allowance needs to be adjusted as the community ages and as needs emerge.





Analysis Date - January 1, 2021



Page 61

Item Parameters - Full Detail

Windows								
Item Number Type Category		33			Measurement Basis Estimated Useful Life			Each 40 Years
		Common Are	a					
		Exterior - Ma	terials		Bas	sis Cost		350.00
Tracking		Logistical						
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bldg A Windo	06/01/1996	06/01/2032	11:05	36:00	15	5,250.00	6,959.69
Common Area	Bldg B Windo	06/01/1996	06/01/2033	12:05	37:00	15	5,250.00	7,133.69

				-				
Location	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
Common Area	Bldg A Windo	06/01/1996	06/01/2032	11:05	36:00	15	5,250.00	6,959.69
Common Area	Bldg B Windo	06/01/1996	06/01/2033	12:05	37:00	15	5,250.00	7,133.69
Common Area	Bldg C Windo	06/01/1996	06/01/2034	13:05	38:00	15	5,250.00	7,312.03
Common Area	Bldg D Windo	06/01/1996	06/01/2035	14:05	39:00	15	5,250.00	7,494.83
Common Area	Bldg E Windo	06/01/1996	06/01/2036	15:05	40:00	15	5,250.00	7,682.20
Common Area	Bldg F Windo	06/01/1996	06/01/2037	16:05	41:00	15	5,250.00	7,874.25
Common Area	Bldg G Windo	06/01/1996	06/01/2038	17:05	42:00	15	5,250.00	8,071.11
Common Area	Bldg H Windo	06/01/1996	06/01/2039	18:05	43:00	15	5,250.00	8,272.89
							42,000.00	60,800.69
Comments								

This component replaces the windows, in aggregate, to maintain the community aesthetics. This component aligns with the *Siding & Trim* component. Window count is average per building.







Items Removed or Left Out of the Study

The following items were either left out of the study due to their inclusion or appurtenance to the annual operating budget, OR subsequently removed upon the Board of Directors (BOD) request. Though each item holds a replacement value, it was determined that the below listed components were not Capital Expenses as traditionally defined.

- 1. Decks & Deck Structures this component falls to the homeowner's responsibility to maintain and replace.
- 2. Garage Door Openers this component falls to the homeowner's responsibility to maintain and replace.

Acompan boundo

NORTHSTAR RESERVES



Glossary of Reserve Study Terms

Garland Meadows Homeowners' Association, Inc. Prepared for the December 31, 2021 Fiscal Year

Terms & Definitions CAI

CASH FLOW METHOD: A method of developing a Reserve Funding Plan where contributions to the Reserve fund are designed to offset the variable annual expenditures from the Reserve fund. Different Reserve Funding Plans are tested against the anticipated schedule of Reserve expenses until the desired Funding Goal is achieved.

COMPONENT: The individual line items in the Reserve Study, developed or updated in the Physical Analysis. These elements form the building blocks for the Reserve Study. Components typically are: 1) Association responsibility, 2) with limited Useful Life expectancies, 3) predictable Remaining Useful Life expectancies, 4) above a minimum threshold cost, and 5) as required by local codes.

COMPONENT INVENTORY: The task of selecting and quantifying Reserve Components. This task can be accomplished through on-site visual observations, review of association design and organizational documents, a review of established association precedents, and discussion with appropriate representative(s) of the association or cooperative.

COMPONENT METHOD: A method of developing a Reserve Funding Plan where the total contribution is based on the sum of contributions for individual components. See "Cash Flow Method".

CONDITION ASSESSMENT: The task of evaluating the current condition of the component based on observed or reported characteristics.

CURRENT REPLACEMENT COST: See "Replacement Cost."

DEFICIT: An actual (or projected) Reserve Balance less than the Fully Funded Balance. The opposite would be a Surplus.

EFFECTIVE AGE: The difference between Useful Life and Remaining Useful Life. Not always equivalent to chronological age, since some components age irregularly. Used primarily in computations.

FINANCIAL ANALYSIS: The portion of a Reserve Study where current status of the Reserves (measured as cash or Percent Funded) and a recommended Reserve contribution rate (Reserve Funding Plan) are derived, and the projected Reserve income and expense over time is presented. The Financial Analysis is one of the two parts of a Reserve Study.

FULLY FUNDED: 100% Funded. When the actual (or projected) Reserve balance is equal to the Fully Funded Balance.



FULLY FUNDED BALANCE (FFB): Total Accrued Depreciation. An indicator against which Actual (or projected) Reserve balance can be compared. The Reserve balance that is in direct proportion to the fraction of life "used up" of the current Repair or Replacement cost. This number is calculated for each component, then summed together for an association total. Two formulae can be utilized, depending on the provider's sensitivity to interest and inflation effects. Note: Both yield identical results when interest and inflation are equivalent.

- 1. FFB = Current Cost X Effective Age / Useful Life or
- 2. FFB = (Current Cost X Effective Age / Useful Life) + [(Current Cost X Effective Age / Useful Life) / (1 + Interest Rate) ^ Remaining Life]

FUND STATUS: The status of the reserve fund as compared to an established benchmark such as percent funding.

FUNDING GOALS: Independent of methodology utilized, the following represent the basic categories of Funding Plan goals:

<u>Baseline Funding</u>: Establishing a Reserve funding goal of keeping the Reserve cash balance above zero.

<u>Full Funding</u>: Setting a Reserve funding goal of attaining and maintaining Reserves at or near 100% funded.

<u>Statutory Funding</u>: Establishing a Reserve funding goal of setting aside the specific minimum amount of Reserves required by local statues.

<u>Threshold Funding</u>: Establishing a Reserve funding goal of keeping the Reserve balance above a specified dollar or Percent Funded amount. Depending on the threshold, this may be more or less conservative than "Fully Funding."

FUNDING PLAN: An association's plan to provide income to a Reserve fund to offset anticipated expenditures from that fund.

FUNDING PRINCIPLES: x Stable Contribution Rate over the Years x Fiscally Responsible

LIFE AND VALUATION ESTIMATES: The task of estimating Useful Life, Remaining Useful Life, and Repair or Replacement Costs for the Reserve components.

PERCENT FUNDED: The ratio, at a particular point of time (typically the beginning of the Fiscal Year), of the actual (or projected) Reserve Balance to the Fully Funded Balance, expressed as a percentage.

PHYSICAL ANALYSIS: The portion of the Reserve Study where the Component Inventory, Condition Assessment, and Life and Valuation Estimate tasks are performed. This represents one of the two parts of the Reserve Study.

REMAINING USEFUL LIFE (RUL): Also referred to as "Remaining Life" (RL). The estimated time, in years, that a reserve component can be expected to continue to serve its intended function. Projects anticipated to occur in the initial year have "zero" Remaining Useful Life.

REPLACEMENT COST: The cost of replacing, repairing, or restoring a Reserve Component to its original functional condition. The Current Replacement Cost would be the cost to replace, repair, or restore the component during that particular year.



RESERVE BALANCE: Actual or projected funds as of a particular point in time that the association has identified for use to defray the future repair or replacement of those major components which the association is obligated to maintain. Also known as Reserves, Reserve Accounts and Cash Reserves. Based upon information provided and not audited.

RESERVE PROVIDER: An individual that prepares Reserve Studies.

RESERVE STUDY: A budget planning tool which identifies the current status of the Reserve fund and a stable and equitable Funding Plan to offset the anticipated future major common area expenditures. The Reserve Study consists of two parts: the Physical Analysis and the Financial Analysis.

RESPONSIBLE CHARGE: A reserve specialist in responsible charge of a reserve study shall render regular and effective supervision to those individuals performing services which directly and materially affect the quality and competence rendered by the reserve specialist. A reserve specialist shall maintain such records as are reasonably necessary to establish that the reserve specialist exercised regular and effective supervision of a reserve study of which he was in responsible charge. A reserve specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein: 1. The regular and continuous absence from principal office premises from which professional services are rendered; except for performance of field work or presence in a field office maintained exclusively for a specific project; 2. The failure to personally inspect or review the work of subordinates where necessary and appropriate; 3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review; 4. The failure to personally be available on a reasonable basis or with adequate advance notice for consultation and inspection where circumstances require personal availability.

SPECIAL ASSESSMENT: An assessment levied on the members of an association in addition to regular assessments. Special Assessments are often regulated by governing documents or local statutes.

SURPLUS: An actual (or projected) Reserve Balance greater than the Fully Funded Balance. See "Deficit."

USEFUL LIFE (UL): Total Useful Life or Depreciable Life. The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.

The above terms and definitions are from the Community Associations Institute (CAI) national standards.